



4/18/2014

AMARILLO  
921 North Bivins  
Amarillo, Texas 79107  
Phone 806.467.0607  
Fax 806.467.0622

ARTESIA  
408 West Texas Ave.  
Artesia, New Mexico 88210  
Phone 575.746.8768  
Fax 575.748.8905

HOBBS  
318 East Taylor Street  
Hobbs, New Mexico 88241  
Phone 505.393.4261  
Fax 505.393.4658

MIDLAND  
2901 State Highway 349  
Midland, Texas 79706  
Phone 432.522.2133  
Fax 432.522.2180

OKLAHOMA CITY  
430 West Wilshire, Suite 10  
Oklahoma City, Oklahoma 73116  
Phone 405.486.7030  
Fax 806.467.0622

SAN ANTONIO  
13111 Lookout Way  
San Antonio, Texas 78233  
Phone 210.265.8025  
Fax 210.568.2191

**Re: Soil Investigation  
Roywell Services Odessa Yard  
2425 East I-20  
Odessa, TX 79766**

To whom it may concern.

Talon/LPE (Talon) was retained by Roywell Services, Inc. (Roywell) to conduct soil investigation activities at the Roywell yard (Site) in Odessa, Texas. The soil investigation was initiated by the Region 7 office of the Texas Commission on Environmental Quality (TCEQ) and the Ector County Sheriff's Department.

Talon personnel conducted sampling activities on March 11, 2014, and March 18, 2014, at the site. Talon personnel collected 31 discreet surface and subsurface soil samples during the two visits. The samples were analyzed at a NELAC certified environmental laboratory in Odessa, Texas for Total Xylene concentration by method BTEX 8021.

During the course of investigation and remediation activities following releases of hydrocarbon based materials, it is not uncommon to observe varying levels of Xylene concentrations in soil for many months after a release. Based on the analytical results of the two sampling events, there is no evidence to suggest a release of Xylene at the subject site.

Please feel free to contact me with any questions.

Respectfully,

Christopher A Spore  
District Manager Talon/LPE  
432-770-0834

ENVIRONMENTAL CONSULTING  
ENGINEERING  
DRILLING  
CONSTRUCTION  
SPILL MANAGEMENT  
GENERAL CONTRACTING